

NOTES:

- OVEREXCAVATION REQUIRED WHEN UNSUITABLE FOUNDATION MATERIALS ENCOUNTERED.
- 2. STRICTLY COMPLY WITH ALL TRENCH SAFETY SYSTEM REQUIREMENTS.
- RESTRAINED JOINT PIPE MAY BE REQUIRED AS DIRECTED BY THE DISTRICT.
- 4. BACKFILL TRENCH IN ACCORDANCE WITH DISTRICT STANDARDS.

SCALE: NTS



UNSUITABLE FOUNDATION EXCAVATION

DATE: 11-2022 DWG: G7